Demolition of existing flat roof attached garage and associated outbuildings to rear of dwelling. Construction of single storey pitched roof side and rear extensions and attached garage. Millbrook House Rainow

application. Confirmation of a decision will be provided to the applicant or agent in writing.

NP/CEC/0924/0948

P5175

P1778

P1778

NP/DDD/1224/1368

NP/DDD/1224/1373

NP/DDD/1224/1375

NP/DDD/1224/1377

NP/DDD/1224/1386

NP/DDD/1224/1405

NP/DIS/0125/0004

NP/DIS/0125/0005

NP/DIS/0125/0013

NP/DIS/0125/0029

NP/DIS/0125/0062

NP/DIS/0125/0063

NP/DIS/0125/0074

NP/DIS/0225/0107

NP/DIS/0225/0139

NP/DIS/0924/0955

NP/DIS/1024/1155

NP/DIS/1124/1181

NP/DIS/1124/1202

NP/DIS/1124/1278

NP/DIS/1224/1321

NP/DIS/1224/1321

NP/DIS/1224/1338

NP/DIS/1224/1341

NP/DIS/1224/1355

NP/DIS/1224/1397

NP/GDO/1224/1304

NP/GDO/1224/1307

NP/HPK/0824/0812

NP/HPK/1224/1385

P9139 + 11619

P9165+748

P11053

P2177

P3103

P9579

P9579

P5463

P2766

P1343

P2079

P2759

P6627

P8564

P10951

P10951

P11359

P4687

P8847

P5509

P7156

P9328

P6406

P9221

P6806 + 3240

P7439 + 9398 +

3435 + 4115 +

11518

P10193

P9521

P10583

P4672

P9788 'Change of use of existing courtyard barns to form one unit of holiday NP/CEC/0924/0999 **Granted Conditionally** accommodation and one ancillary dwelling. Replacement of existing implement shed with new stone built unit. Refurbishment of existing detached storage barn. External alterations to existing farmhouse with introduction of bi-fold doors. Retention of existing site caravan for temporary site accommodation P5175 **Torgate Farm** Wildboarclough NP/CEC/0924/0999 'Change of use of existing courtyard barns to form one unit of holiday **Granted Conditionally**

Applications determined by the Head of Planning between 01/02/2025 and 28/02/2025

Granted Conditionally

Granted Conditionally

Accept Conditionally

Granted Conditionally

Granted Conditionally

LDC Granted

Refused

Condition/s Partly Discharged

Condition/s Partly Discharged

Condition/s Partly Discharged

Condition/s Partly

Condition/s Partly Discharged

Condition/s Partly Discharged

Condition/s Partly Discharged

Condition/s Partly Discharged

Condition/s Fully Discharged

Condition/s Partly

Condition/s Partly Discharged

Condition/s Partly Discharged

Condition/s Partly Discharged

Condition/s Partly

Condition/s Partly Discharged

Granted Conditionally

Granted Conditionally

Granted Conditionally

Granted Conditionally

Discharged

Discharged

Discharged

We have taken reasonable steps to ensure the information provided by us on this website is accurate at the time you view it. However, we cannot and have not checked the accuracy of all information provided by outside sources or by the providers of other information or of other parties linked to or from the website. We would recommend that you contact the Authority to check the status of an application and for confirmation regarding any decision made on an

accommodation and one ancillary dwelling. Replacement of existing implement shed with new stone built unit. Refurbishment of existing detached storage barn. External alterations to existing farmhouse with introduction of bi-fold doors. Retention of existing site caravan for temporary site accommodation **Torgate Farm** Macclesfield Forest NP/CEC/0924/1029 Conversion of the existing shippon to C3 use class and associated alterations. Accept Conditionally Smithy House Farm Wincle NP/CEC/0924/1029 Conversion of the existing shippon to C3 use class and associated alterations. **Accept Conditionally Smithy House Farm** Heaton

NP/CEC/1224/1366 External: widening of doorway into Gardens Public WCs and addition of sliding **Granted Conditionally** external door, replacement of rooflights and parapet gutter linings. Internally: alterations to enlarge and improve disabled WC facilities and provide a dedicated baby change room. Lyme Hall Lyme Handley **Granted Conditionally** Listed Building consent - External: widening of doorway into Gardens Public WCs and addition of sliding external door, replacement of rooflights and parapet gutter linings. Internally: alterations to enlarge and improve disabled WC facilities and provide a dedicated baby change room. Lyme Hall Lyme Handley

P2741 NP/CEC/1224/1367 purchase and be able to use portable roll on/off cricket nets . approx 7 m long x 2.7m high x 3m wide. to be rolled on to the ground for cricket practise, then rolled back to the side of the pavilion to store. Playing Field Car Park Youlgrave Demolition of rear porch; erection of single storey rear extension; external alterations and redecoration, including erection of external fire escape; provision of extract flue; formation of new service yard with GRP unit; formation of access ramp from extension to garden and internal alterations and cosmetic

P2741 Permission not required NP/DDD/0125/0027 P9251 **Granted Conditionally** NP/DDD/0523/0543 refurbishment and redecoration. P2952 **Bulls Head Hotel** Ashford NP/DDD/0523/0544 Listed Building consent - Demolition of rear porch; erection of single storey rear **Granted Conditionally** extension; external alterations and redecoration, including erection of external fire escape; provision of extract flue; formation of new service yard with GRP unit; formation of access ramp from extension to garden and internal alterations and cosmetic refurbishment and redecoration. P2952 **Bulls Head Hotel** Ashford

Change of use to a residential dwelling and garden, rebuilding of single storey Refused element along with new access track Land to the west of Stanedge Road Bakewell Installation of a compressor shed and compressor. **Ballidon Quarry Ballidon** Construction of a new extension to an existing agricultural barn for housing

NP/DDD/1024/1069 P1319 NP/DDD/1024/1076 **Granted Conditionally** P3893 + 7059 NP/DDD/1124/1253 **Accept Conditionally** P3331 **Broadmeadow Farm** Harthill NP/DDD/1224/1348 Proposed new glazed screen behind existing double barn doors, new first floor **Granted Conditionally** window and four new rooflights along north aspect of existing roof. P4329 Thornleigh Hathersage NP/DDD/1224/1362 Conversion of agricultural barn to open market dwelling. Refused Barn and Croft to east of Robin Hey off B6465 Wardlow

Listed Building consent - Replacement of 3 no. pvc windows with timber and

Refurbishment of clubhouse and porch extension, replacement of plant room

Lawful Development Certificate for existing development comprising of an air

Retrospective consent to retain an agricultural building for the use of housing

Discharge of conditions 5, 6, 7, 8, 9, 10 and 13 on NP/DDD/0623/0614

retention of existing satellite dish in current position.

Bank House Guest House

and changing rooms to swimming pool

1-2 Victoria Terrace, Spindle Cottage

Erection of agricultural building.

Single storey extension to the rear of property.

Land to the East of Monyash off south side of B5055

Discharge of condition 3 on NP/DDD/0624/0641.

Discharge of condition 5 on NP/DDD/0724/0747

Discharge of condition 6 on NP/DDD/0623/0695

Discharge of condition 4 on NP/DDD/1019/1101

Discharge of condition 7 on NP/DDD/1019/1103

Discharge of condition 4 on NP/SM/0224/0180

Discharge of Condition 8 on NP/DDD/1024/1085

Discharge of condition 11 on NP/DDD/1024/1053.

Land about 375m to the East of Pyeclough Farm

Discharge of conditions 5 on NP/DDD/0623/0619

Discharge of Condition 4, 5 and 6 on NP/DDD/0424/0452

Discharge of conditions 3 b and c, 14 and 21 on NP/DDD/1221/1346

Discharge of conditions 3, 4, 6, 9, 12 & 15 on NP/DDD/1023/1299

Discharge of conditions 3, 4, 6, 9, 12 & 15 on NP/DDD/1023/1299

Footbridge to the North West of Cressbrook Mill

Footbridge to the North West of Cressbrook Mill

Discharge of Condition 4 on NP/SM/0322/0438

Discharge of condition 5 on NP/DDD/1024/1043

Discharge of condition 7 on NP/SM/0822/1111.

Outbuilding with associated patio and landscaping

Discharge of Conditions 8 and 9 to NP/HPK/0823/0942

GDO Notification - Agricultural building for the storage of fodder and

implements, with associated hardstanding and construction of traditional

GDO Notification - Agricultural building to create a covered silage clamp to

Garden Room or 'studio' to side of house, in space left by removal of oil tank.

Discharge of conditions 3, 5 & 6 on planning application NP/SM/0624/0660'

Discharge of Condtions 2, 3, 5, 7, 8, 11, 14 and 15 on NP/HPK/0524/0478

Lime Kiln 65m From Budgetts Farm

Ashbourne Heights Holiday Park

Hartington Town Quarter

Fenny Bentley

Great Longstone

Rosebank Farm

source heat pump.

Sycamore Cottage

Rose Farm Cottage

Bagshaw House

Tideswell

Rowland

livestock.

Monyash

Grindlow

Eyam

Stoneridge

Winster

Calver

Calver

Grindon

2 Bank View

Tideswell

Bibury

Curbar

Heathylee

Devonshire Farm Peak Forest

Rowsley House

Bakewell

Bubnell Hall Baslow & Bubnell

Former Hosiery

Fynderne House Alstonefield

Hollow Farm Harthill

School House Wormhill

Lower Fleet Green Fawfieldhead

agricultural track.

Overton Hall Farm Whaley Bridge

Cracken Edge

Brookfield Edale

Cherry Blossom Farm Stoney Middleton

replace the bale storage area.

Chinley, Buxworth & Brownside

Litton

Litton

Hartington Nether Quarter

Sunnybank House

Knouchley Farm Cottage

Knouchley Farm Cottage

P9202	Certificate of Lawfulness for this development is therefore sought. Robin Hill Hope	
NP/NMA/0125/0035 P4518 + 3748	Non-material amendment on NP/DDD/1223/1511: Change a 3 door patio door system (no dimensional change) to a 2 door patio door system Belmont House Baslow & Bubnell	Amendments Accept
NP/NMA/0225/0104 P6601	Non Material Amendment to NP/SM/0123/0037 - a minor amendment to the South West elevation of approved cattle shed. Pump Farm Warslow and Elkstones	Amendments Accept
NP/NMA/0225/0123 P4910	Non-material amendment to NP/DDD/0424/0427: Change external doorway into an external window in the same location with smaller dimensions than the approved door. Sinclair House	Accept
NP/S/1224/1339 P2572	Proposed retention of timber pergola within garden curtilage of host cottage. Moscar Cross Cottages Bradfield	Granted Conditionally
NP/S/1224/1342	Conversion of garage to study and bathroom space, with two windows in place of garage door, new glazing to sides and rear. Inclusion of rooflights to garage roof; form a glazed link between garage and house	Granted Conditionally
P3835 NP/SM/1024/1106 P5509	Reservoir Cottages Sheffield Form openings in the internal masonry walls for heating system distribution pipework (installation of boiler and radiators previously approved application reference NP/SM/0822/1111). Form opening in north external wall of lounge for air duct. Alter fireplace FP2 (parlour) for new biomass room heater. And replacement of rear door Lower Fleet Green	Granted Conditionally
NP/SM/1024/1126 P11383	Fawfieldhead Listed Building consent - Retention of alterations to ground floor and staircase. Lower Damgate Farm	Granted Conditionally
NP/SM/1024/1147 P	Ilam Advertisement consent - Erection of sign Dove Dale	Granted Conditionally
NP/SM/1124/1172 P983	S.73 application for the removal of condition 3 on NP/SM/0322/0326 The Croft Alstonefield	Granted Conditionally
NP/SM/1124/1279 P6822	Installation of modern, domed fountain within existing fountain bowl. Ilam Hall Ilam	Granted Conditionally
NP/SM/1124/1280 P6822	Listed Building consent - Installation of modern, domed fountain within existing fountain bowl. Ilam Hall	Granted Conditionally
NP/SM/1124/1285 P538	Proposed side extension and front entrance porch Meadowfold Butterton	Granted Conditionally
NP/SM/1224/1320 P892	Listed Building consent - The installation of stainless steel connections between the separate stone segments of the parapet - and the tying back of these connections to the roof structure with stainless steel straps. The Grapes Longnor	Granted Uncondition
NP/SM/1224/1353 P2228	S. 73 application for the removal or variation of condition 2 on NP/SM/0822/1005 The Old Nick Cottage Warslow and Electones	Granted Conditionally
NP/SM/1224/1361 P11387	Warslow and Elkstones Erection of a stable building with associated landscaping. Land on Grindon	Granted Conditionally
NP/SM/1224/1365 P6822	S.73 application for variation of condition 1 of NP/SM/0222/0271 Ilam Hall Ilam	Granted Temporarily
NP/TCA/0125/0010 P6191	Various tree works including the repollarding of an existing avenue of lime trees. Longstone Hall Great Longstone	Accept
NP/TCA/0125/0096 P418	T10 Sycamore (Acer pseudoplatanus) reduce squirrel grazing damaged branches back to site boundary. G3 Screen (mixed species) remove storm damaged branches and stems. Recreation Ground Kettleshulme	Accept
NP/TCA/0225/0108	T1 Reduce beech tree on far left by 4-5m on limb with previously failed wound. Then lift the front over the graveyard. And reduce height bring the tree in line with the others. G1 Lift 5-6m and reduce back, over extended limbs over gravestones of the group containing 4 remaining large trees T2 Remove dead Elm	Accept
P9949	T3 Reduce pine hight by 2-3m G2 Remove one holly and reduce the remaining holly to 2m to allow sycamore to grow and still maintaining screening for the patio. The Old Vicarage	
NP/TCA/0225/0111 P1827	Ashford Scots Pine. Fomer owners had 50% of trunk heighr emoved. Poor condition with excessive shading. Root system putting pressure on a retaining wall. No birds nesting. Application to fell in full. Ivy Cottage Thorpe	Accept
NP/TCA/0225/0112 P6963	T4, T5, T6 & T7 are located at the above property, T1 , T2 & T3 are located in a belt of woodland approximately 300 yards away. See separate map. Alsop Hall Eaton & Alsop	Accept
	tree locations are also included. Jason from Roots & Shoots has provided numerous replanting options to increase the amenity and wildlife value of the property. It is our intention to replant the area to replace the beech and slender pines. Initially we intend to plant a minimum of three common Alders and then decide the best place to replant some more species best suited to fit around the alders. Removal of T001 (dying pine at top of garden) and the small adjacent holly (shown by yellow arrow on photo). See tree report Removal of T004 (sycamore at northwest garage corner) (see site map page 5 & photograph page 16 in tree report) Removal of T006 (sycamore beside entrance) (see photo and site map - page 5 tree report) Removal of two roadside pines (identified by red crosses/arrows on photo) Jon Coe has seen. Removal of T005 (dying beech – see photo and tree report) and removal of the	
P6406 NP/TCA/0225/0129	row of tall slender pines to the south of this (identified by red outline on photo). Cracken Edge Chinley, Buxworth & Brownside Felling to ground level and clearance of one Whitebeam ornamental tree - see CC1 for photos and location.	Accept
P1013 NP/TCA/0225/0131	Christmas Cottage Youlgrave Blue spruce - T1 - fell Prunus - T2 - Crown reduce by 2 metres	Accept
P6597 NP/TCA/0225/0133	Netherfield Bakewell Elm T1 - Fell	Accept
P5592 NP/TCA/0225/0134	Hawthorn T2 - Fell Sherwood House Tideswell Horse Chestnut T1 - Fell	Accept
	Spruce T2 - Fell Larch T3 - Fell Ash T4 - Fell Sycamore T5,6,7 - Fell Ash T8 - Pollard to 10 metres	
P5770 NP/TCA/0225/0134	Thornbridge Hall Ashford Horse Chestnut T1 - Fell Spruce T2 - Fell Larch T3 - Fell Ash T4 - Fell Sycamore T5,6,7 - Fell Ash T8 - Pollard to 10 metres	Accept
P5770 NP/TCA/0225/0141	Thornbridge Hall Great Longstone Tree surgery works located within the gardens of Beechcroft, Baslow, Peak District, DE45 1RZ, including the following:	Accept
	Please find the relevant What 3 Words locations for reference below. T1 - Early Mature Apple Tree - failed significant branch - propped within the crown - remove failed branch Location - alternate.radar.gravest	
	T2 - Young Cherry Tree - remove to ground level. Location - asset.crops.detriment	
	T3 - Mature Cherry - significant loss of vitality - remove to ground level. Location - enough.bonfires.spice T4- Mature Laburnum - failing co-dominant stem - remove Location - thumbnail beakers compounds	
	Location - thumbnail.beakers.compounds T5 - Early Mature Lime Tree Group G2 - Early Mature Lime x4 - failure of two significant stems hung up within the crown adjacent to the perimeter fence. Some staining potentially Phytophthora causing die back within a southerly aspect.	
P1556	Remove the failed branches and any significant deadwood. T6 - Mature Hornbeam - inspect significant hollow/cavity located at 4-5 metres from ground level. Location - rich.president.afterglow Beechcroft Cottage	
NP/TCA/0225/0162 P6521	Removal of lower overhanging branches from the neighbours Oak tree located in the rear courtyard. Forresters House	Accept
NP/TCA/0225/0168	Eyam (T1) - Crown reduce the laburnum to the previous pruning levels (up to 2.5m) well below the phone wire. (T2) - Repollard the Cottoneaster to the obvious knuckles (up to 2.5m) well below the phone wire. Knowle Cottage	Accept
P2535 NP/TCA/0225/0169	Knowle Cottage Bamford T1 Goat willow. Fell to ground level T2 Cherry reduce by 2m. Turnock House	Accept
P566 NP/TCA/0225/0178	Turnock House Butterton 2 Himalayan birch on terrace - Raise crowns to approximately 2m by removing lower horizontal secondary branches to create a more upright	Accept
P4269	form Yew branches growing towards Himalayan birch and over grassed area and path - Prune to clear Himalayan birch by approximately 2m and prune back overhang over garden by approximately 2m whilst maintaining a natural shape and not a vertical side Bank House Winster	
NP/TCA/0225/0187 P9771	Winster Fell dead ash tree and clear the bank. Access is very difficult and we want to do all this work together. School House Fenny Bentley	Accept

Applications determined by the Head of Development Control between 01/02/2025 and 28/02/2025

NP/TPO/0225/0105

TPO61 Sycamore tree. Location - just South of house - see aerial view. Resons for work: tree in structural decline & presents risk due to limbs falling off at random, not in storms/gales. John Coe has inspected and proposed works on tree to prolong its life while keeping it and us safe. His email to me on 18.11.24 is extracted on next page. His proposed works are shown on the attached photo which we would follow.

'Appropriate tree work it can be retained for many years yet as a landscape feature and a significant ecological habitat. I took various photographs, but I think we can simplify it down to the single one attached which illustrates all that is required. As viewed from the southeast side of the tree. To give the tree the best chance of recovering, we discussed that you will retain as much as possible of the many current slender growth shoots (though a lot will inevitably be lost). Once the tree has had 3 or so years to form new shoots lower down, the existing retained ones can be pruned back where required (this will require

an application at that time).

P8488 Town Head Farm

Longnor

NP/TPO/0225/0120 H1 - staggered line of laurel trees - reduce down to 8' from 22' as overgrown.

H2 - staggered line of conifers - reduce height from 23' to 10'.

T1 - reduce conifer and prune back away from house.

T2 - crown reduce yew tree by 30%.

P4177 Badgers Heights

Bakewell

NP/TPO/0225/0120 H1 - staggered line of laurel trees - reduce down to 8' from 22' as overgrown.

H2 - staggered line of conifers - reduce height from 23' to 10'.

T1 - reduce conifer and prune back away from house.

T2 - crown reduce yew tree by 30%.

P4177 Badgers Heights

Bakewell

NP/TPO/0225/0157 T1 Sycamore, fell to ground level on corner of barn opposite entrance to

Ringstone Farm.

P5989 New Ringstones Farm

New Mills

NP/TPO/0225/0180 Tree is T3 on the TPO and described within as a Mature Thorn. It is still

standing but branches resting on the Mature Oak T4.

Photos provided to peak park under enquiry ENQ/51945.

P4273 Oakes Farm House

Bradfield

Accept Conditionally

Accept

Accept

Permission not required

Accept Conditionally